

POWERGEAR®

Version:4.00
























≥40mm 3 6 5





Troubleshooting

Abnormal: The circuit of the track system has no power or the line voltage exceeds the nominal value, please check whether the following exceptions exist in the installation:

- 1. Please ensure that the "convex" reinforcement position inside the track system is consistent with the direction of the "concave" groove of the connector, and reverse installation is prohibited;
- 2. Please ensure that the connector connection is firm, no loose and falling off, and installed in place with the track to prevent virtual connection;
- 3. Please ensure that the wiring inside the power supply box is wired according to the regulations.

Disclaimer

- 1. It is forbidden to apply paint, glue, etc. to this product.
- 2. This product is suitable for indoors, not outdoors.
- 3. It is recommended to use POWERGEAR track system, compatibility with other track system is not guaranteed.
- 4. If the structure or wiring of this product is not used/modified according to the instructions, resulting in damage to this product or related products, POWERGEAR doesn't continue to maintain the after-sales commitment.
- 5. Product optimization and version upgrade will not be prior noticed. Please refer to the actual product received. If you have any questions, please contact our sales staff in time.
- 6. POWERGEAR reserves the right of final interpretation of this product.